

Field Notes:

Date: Tuesday, February 20, 2007

11:00 - Arrived at Site

Met with Dennis of Terra, Keith Krawczyk of MDEQ, Chase Fortenberry of GP, Pat McGuire and Tony of BBL

Toured site with group

An area in Refuse Area near lift station where residuals were encountered, though utility lines are positioned above it. Residuals were tested and were negative for PCBs.

Ordered test pit on other side of utility poles to determine extent.

Was told the fill material being used met requirements for vegetation, but not Work Plan requirements, because approved vegetation for the site (list approved for Plainwell) did need the requirements in the work plan.

14:30 - Drove to Refuse area and Oxbow Area for photos

IMG_0629

IMG_0630

IMG_0631

IMG_0632

IMG_0633

IMG_0634

IMG_0635

15:00 - Departed site.













